

April 9, 2019

CE LITE-50

Version 1.20

Release date: April 9, 2019

- Modification
 1. When the media sensor width is adjusting, the error was not checking.
The error will display when adjustment value was incorrect.
 2. Corresponded for the new version of xpf file format.
- Fixed problem
 1. When position was moved by position key for the bar code file data, movement of position was not stopped.
 2. When the CE LITE-50 sent the data to the PC more than 192 bytes, there was possibility for data lost.

Version 1.10

Release date: March 28, 2018

- Modification
 1. Countermeasures for vibration noise (further improvement of Ver.1.05).
- Fixed problem
 1. Home position moved if career sheet was load repeatedly.
 2. Sometimes the media was not pulled into the CE LITE-50 when loading.
 3. Sometimes Off-scale was displayed on the LCD during feed operation after plotting.
 4. Off-scale was displayed with some plot data.
 5. Sometimes part of the test cut was not be cut in tangential mode.

Version 1.05

Release date: March 7, 2018

- Modification
 1. Countermeasures for vibration noise.
- Fixed problem
 1. Fan motors did not stop after failing to read the barcode if it returns to the HOME screen without retrying.
 2. If "Graphtec Segment Area Type 1" is selected as the registration mark with CM4 (Windows / Mac), Graphtec Pro Studio (Windows), or Graphtec Studio (Mac), a registration mark detection error occurs with the additional marks.

3. Media dropped after segment registration mark of a cutting job was finished when the check box of advance after plot was checked in the CM4.
4. It rarely hangs with displaying "PROCESSING" when the copy function is ON.

Version 1.03

This version was not released.

- Fixed problem
 1. Barcode cannot be read stably.

Version 1.00

Release date: December 28, 2017

- Initial version

End